

The new plug-in connecting system for GHIELMETTI-Patch Bays


Installation instructions

GHIELMETTI Patch Panels may be connected on a very fast and easy way to your individual cabling system.

Therefore GHIELMETTI developed the new Solder-Lug-Connector **GAS 323 LA C**.



Solder-Lug-Connector
GAS 323 LA C
673.910.311.01



Interconnecting cables:

30 cm	673.910.295.03
60 cm	673.910.295.06
100 cm	673.910.295.00

Take note of following instructions for mounting the connectors to your cable:

1. After soldering, the cable have to be fixed by a cable tie onto the connector.
2. „G“ (GND) indicate signal ground or cable shield.
3. Fix the cable to a cable tree and the cable tree to the cable bar.

Pin out of the back side of the patch panel

GND - +
G b a

