










ASSEMBLY INSTRUCTION

NC3FXX-HD & NC3MXX-HD | XLR Cable Connector

- A** Slide the rubber sealing (1) and the boot (2) onto the cable.
- B** Prepare cable as shown.
- C** Insert wires into the terminals and solder them.
- D** Put chuck onto the cable.
Attention: Pay attention to the guiding key.
- E** Slide insert and chuck together into the housing.
- F** Turning the bushing onto the connector.
- 
- 
- 
- 
- 
- 

► Rubber sealing assembly see on page 2.



G Put the assembly tool onto the female connector over the end of the bout (as shown in picture).

H Push the rubber sealing onto the assembly aid.
Attention: Pay attention to the position of the Push (see the picture).

I Hold the cable and pull the assembly tool jerkily off the connector (the sealing jacket is pulled in position).

► Finish

ASSEMBLY OF MALE CONNECTOR



A Repeat the steps

F

G Push the rubber sealing onto the plug.


► Finish

ORDER OF ASSEMBLY


NC3FXX-HD



Rubber sealing




bushing



chuck





insert



housing

NC3MXX-HD



NEUTRIK AG
NEUTRIK Zürich AG
NEUTRIK USA Inc.
NEUTRIK (UK) Ltd.

LI
CH
USA
UK

T: +423 / 237 24 24 F: +423 / 232 53 93
T: +41 44 / 736 5010 F: +41 44 / 736 5011
T: +1 732 / 901 9488 F: +1 732 / 901 9608
T: +44 1983 / 811 441 F: +44 1983 / 811 439

NEUTRIK Vertriebs GmbH
NEUTRIK France
NEUTRIK Tokyo Ltd.
NEUTRIK Hong Kong Ltd.

DE/NL/AT/DK
FR
JP
HK

T: +49 8131 / 280 890 F: +49 8131 / 280 830
T: +33 1 / 4131 6750 F: +33 1 / 4131 0511
T: +81 3 / 3663 4733 F: +81 3 / 3663 4796
T: +852 / 2687 6055 F: +852 / 2687 6052